HITACHI

LIST NO. F814

ELECTRIC TOOL PARTS LIST

■ CORDLESS DRIVER DRILL
Model FDS 12DV

1997・7・10
(E1)



PARTS

ITEM NO.	CODE NO.	DESCRIPTION	NO. USED	REMARKS	
1		NAME PLATE	1		
2	308-511	– DRIVER BIT 4MMX50L	1		
3	314-864	HOUSING (A).(B) SET	1		
4	309-614	TAPPING SCREW (W/FLANGE) D3X14	7		
5	309-611	BIT HOLDER (B)	1		
6	309-617	STRAP	1		
7	980-836	FLAT HD. SCREW (LEFT HAND) M5X20	1		
8	312-516	DRILL CHUCK 10TLRD – N (W/O CHUCK WRENCH)	1		
9	309-599	CAP	1		
10	309-600	SPRING HOLDER	1		
11	309-601	SPRING	1		
12	309-602	THRUST PLATE	1		
13	309-603	STEEL BALL	4		
14	309-604	SPINDLE AND GEAR SET	1		
15	309-607	SHIFT ARM	1		
16	309-608	SHIFT KNOB	1		
17	309-609	SHIFT SPRING	1		
18	309-606	TAPPING SCREW D3X8	4		
19	309-612	BIT HOLDER (A)	1		
20	308-510	+DRIVER BIT NO.2X50L	1		
21	314-863	MOTOR	1		
22	314-865	DC – SPEED CONTROL SWITCH	1		
23		HITACHI LABEL	1		
24		MARK PLATE	1		
25		FT SCREW M3X10	2		
26	310-156	FIN ASS'Y	1	INCLUD.25	
27	310-157	TERMINAL	1		
28	314-602	BATTERY FEB12	1		

STANDARD ACCESSORIES

ITEM NO.	CODE NO.	DESCRIPTION	NO. USED	REMARKS	
501	314-866	CASE	1		
502		CHAGER (UC12SC)	1		

* : ALTERNATIVE PARTS

Printed in Japan 7 – 97
(970703 N)